

EFFECT OF DEFECT LENGTH UPON  
BURST CAPACITY OF COMPOSITE  
REPAIRED PIPE

LIM KAH QI

B. ENG (HONS.) CIVIL ENGINEERING

UNIVERSITI MALAYSIA PAHANG



## **STUDENT'S DECLARATION**

I hereby declare that the work in this thesis is based on my original work except for quotations and citations which have been duly acknowledged. I also declare that it has not been previously or concurrently submitted for any other degree at Universiti Malaysia Pahang or any other institutions.

---

(Student's Signature)

Full Name : LIM KAH QI

ID Number : AA15217

Date :

EFFECT OF DEFECT LENGTH UPON BURST CAPACITY OF COMPOSITE  
REPAIRED PIPE

LIM KAH QI

Thesis submitted in partial fulfillment of the requirements  
for the award of the  
B. Eng (Hons.) Civil Engineering

Faculty of Civil Engineering & Earth Resources  
UNIVERSITI MALAYSIA PAHANG

MAY 2019

## **ACKNOWLEDGEMENTS**

The completion of this study could not have been possible without the assistance of so many people whose names may not all be enumerated. Their contributions are sincerely appreciated and gratefully acknowledged.

However, I would like to express my deep appreciation and indebtedness to my beloved supervisor, Dr. Lim Kar Sing. I would like to express my special thanks of gratitude to him for his endless support, kind and the knowledge he taught me throughout my study.

A debt of gratitude is also owed to my entire friends, especially Mr. Tay Hong Wei and Miss Leong Kah En for always providing help and sharing the idea and knowledge throughout my project.

Last but not least, I would like to thank my mom and brother – Madam Wan Sau Kei and Mr. Lim Kah Hao for the support, either morally, financially or physically throughout the days.

## ABSTRAK

Sistem saluran paip adalah salah satu infrastuktur yang amat penting dalam industri petrokimia kerana ia digunakan untuk mengangkut petroleum dan gas. Walaubagaimanapun, kerosakan dan kemerosotan paip akan berlaku beberapa tahun selepas ia digunakan, terutama berlakunya pengaratan pada saluran paip yang akan menipiskan ketebalan saluran paip dan kekuatan paip dan seterusnya menyebabkan kegagalan apabila baki kekuatan paip tidak mampu menahan tekanan operasi saluran paip tersebut. Oleh itu, kerja pembaikan paip amat diperlukan untuk menambahkan kekuatan paip, contohnya, dengan menggunakan komposit polimer diperkuat gentian (*FRP*). Kod pembaikan yang digunakan untuk menentukan baki kekuatan paip yang berkarat tidak memasukkan geometri kepanjangan dalam pengiraannya yang amat berbeza dengan kod penilaian. Dalam kajian ini, tekanan letus paip yang diperbaiki komposit akan dikaji dengan pelbagai kecacatan kepanjangan yang berlainan. Kajian ini dijalankan dengan menggunakan kaedah analisis unsur terhingga pada pelbagai paip yang mengalami kerosakkan dengan saiz panjang yang berlainan. Keputusan telah menunjukkan bahawa perbezaan tekanan paip ialah 15.59% dan ini telah menunjukkan bahawa geometri kepanjangan mempunyai kesan pada tekanan letus paip yang diperbaiki komposit. Penemuan ini sangat berguna untuk mengoptimalkan reka bentuk sistem pembaikan yang sedia ada.

## **ABSTRACT**

Pipeline system is one of the infrastructures that are essential in petrochemical industries as it is used to transport oil and gas. However, pipelines will start to damage and deteriorate after being used for some years, especially the happening of corrosion which will reduce the thickness of pipeline and the remaining strength of the pipe and consequently lead to failure once the remaining strength is unable to withstand operating pressure of the pipeline. Hence, additional strength from repairing job needs to be provided, for instance, by using fibre-reinforced polymer (FRP) composites. Unlike the assessment codes, the repair code that is used to determine the remaining strength of the corroded pipe does not include the defect geometries such as defect length. In this study, burst pressure of the composite repaired pipeline with different defect lengths and the effect of the defect length upon the burst capacity of composite repaired pipe is investigated. The study is carried out by a finite element analysis (FEA) on various defective pipe with different defect length size. The results show that the difference of the burst pressure subjected to various defect length is 15.59% and this has proved that there is an effect of defect length upon the burst capacity of composite repaired pipe. This finding can be very useful for optimizing the existing repair design.

## **TABLE OF CONTENT**

**DECLARATION**

**TITLE PAGE**

**ACKNOWLEDGEMENTS** **ii**

**ABSTRAK** **iii**

**ABSTRACT** **iv**

**TABLE OF CONTENT** **v**

**LIST OF TABLES** **viii**

**LIST OF FIGURES** **ix**

**LIST OF SYMBOLS** **x**

**LIST OF ABBREVIATIONS** **xi**

**CHAPTER 1 INTRODUCTION** **1**

1.1 Overview 1

1.2 Background of Study 2

1.3 Research Problem 2

1.4 Research Objectives 3

1.5 Research Scope 3

1.6 Importance of Study 3

**CHAPTER 2 LITERATURE REVIEW** **5**

2.1 Introduction 5

2.2 Overview 5

2.3 Defect of Pipelines 6

2.4	Repair Techniques	7
2.5	Stresses Acted on Steel Pipes	9
2.6	Current Codes and Practices	10
<b>CHAPTER 3 METHODOLOGY</b>		<b>13</b>
3.1	Introduction	13
3.2	Modelling Bare and Corroded Steel Pipes	14
3.3	Material Properties Assignment	15
3.4	Load and Boundary Conditions Assignment	16
3.5	Meshing of Steel Pipe	16
3.6	Execution and Validation of Bare Pipe Models	18
3.7	Modelling Composite Repaired Steel Pipes	18
3.8	Modelling of Putty	18
3.9	Modelling Composite Wrap	20
3.10	Parametric Study	20
<b>CHAPTER 4 RESULTS AND DISCUSSION</b>		<b>22</b>
4.1	Introduction	22
4.2	Finite Element Analysis	22
4.2.1	Finite Element Analysis of Half-D Model	22
4.2.2	Finite Element Analysis of D Model	23
4.2.3	Finite Element Analysis of 2D Model	24
4.3	Burst Pressure Test	25
<b>CHAPTER 5 CONCLUSION</b>		<b>28</b>
5.1	Overview	28



5.2	Conclusions	28
5.3	Significant of Research Contribution	29
5.4	Recommendations	29
<b>REFERENCES</b>		<b>30</b>

## **LIST OF TABLES**

Table 3.1	Defect Geometry of Defective Pipe	20
Table 3.2	Geometry of Putty and Composite Wrap	21

## LIST OF FIGURES

Figure 2.1	Defect Geometries in Schematic Defective Pipelines	7
Figure 2.2	Full-encirclement steel sleeve and repair clamp	8
Figure 2.3	Clock Spring ® FRP composite repair system with FRP composite (1), Interlayer adhesive (2), and Infill material (3)	9
Figure 2.4	Direction of Hoop and Longitudinal Stress	9
Figure 3.1	Flow Chart of Research Methodology	14
Figure 3.2	Geometry of Bare Pipe	15
Figure 3.3	Geometry of Defective Pipe	15
Figure 3.4	Internal Pressure and Boundary Condition	16
Figure 3.5	Process in achieving Structural Mesh	17
Figure 3.6	Example of a Meshed Defective Pipe	17
Figure 3.7	Sequence for Putty Location Translation	19
Figure 3.8	Example of a Meshed Putty	19
Figure 4.1	Stress Contour Plot for the <i>Half D</i> composite repaired-pipe model	23
Figure 4.2	Stress Contour Plot for the <i>D</i> composite repaired-pipe model	24
Figure 4.3	Stress Contour Plot for the <i>2D</i> composite repaired-pipe model	25
Figure 4.4	Result of Defect Length on Burst Pressure	26
Figure 4.5	Effect of Defect Length on Burst Pressure	27

## LIST OF SYMBOLS

$D$	<i>Outer Diameter of Pipe</i>
$t$	<i>Pipe Wall Thickness</i>
$\sigma_y$	<i>Material Yield Strength</i>
$\sigma_u$	<i>Ultimate Tensile Strength</i>
$\sigma_a$	<i>Axial Stress</i>
$\sigma_r$	<i>Radial Stress</i>
$\sigma_h$	<i>Hoop Stress</i>
$L$	<i>Defect Length</i>
$d$	<i>Defect Depth</i>
$r$	<i>Radius of Pipe</i>
$w$	<i>Defect Width</i>
$P$	<i>Burst Pressure</i>
$M$	<i>Bulging Stress Magnification Factor</i>
$t_s$	<i>Remaining Wall Thickness</i>
$P_s$	<i>Maximum Allowable Operating Pressure</i>
$s$	<i>Specific Minimum Yield Strength</i>
$\varepsilon$	<i>Maximum Strain</i>

## LIST OF ABBREVIATIONS

<i>FEA</i>	<i>Finite Element Analysis</i>
<i>FRP</i>	<i>Fibre Reinforced Polymer</i>
<i>CFRP</i>	<i>Carbon Fibre Reinforced Polymer</i>

## **CHAPTER 1**

### **INTRODUCTION**

#### **1.1 Overview**

Pipelines act as a transport element in petrochemical industry which normally use in offshore and placed underground. This infrastructure is important in human life, it help in delivering oil and gas that has been produced into different products that we used. For instance, the heat supply for stoves, fuel supplies for transportation and run the machine to make the household product. The study of National Association of Manufacturers (NAM) had also estimated that the crude oil pipelines alone created over 200,000 jobs and over \$21.8 billion in Gross Domestic Product in 2015 (National Association of Manufacturers, 2015). This had shown that pipeline infrastructure is also important in moving the country's economic (Lim et al., 2015).

There are a lot of pipeline accidents all around the world over the years including United States who has the longest network of pipeline in the world with 240,711km of the pipeline network is used to transport the petroleum products and 1,984,321 km in transporting the natural gas to make the total length of 2,225,032km (Central Intelligence Agency, 2013). After years in service, pipeline will experience deterioration and a deteriorated pipeline may subsequently fail if no proper action is taken. Hence, monitoring and inspecting of pipeline will be carried out to discover the failures or the deterioration of the pipeline system. One of the common ways for pipeline inspection is done by intelligent pigging to gather important data of the pipeline such as location and geometries of defects. Without carry out the inspection and repairing work of the pipe, the deterioration of the pipeline may cause pipe failures such as leaking and explosion.

## **1.2 Background of Study**

The environment surrounding the pipelines will cause defect on the pipelines due to several factors and subsequently affect the service strength and its service life. There are several types of defect in the pipelines system which include the geometrical defect, defect in metal loss, planner discontinuities and change in metal, and all of these defects will bring effect to the pipelines system (Abdel-Alim, 2018). All of these defects will affect the remaining strength of the pipeline and its service life and performance.

There are a lot of method to repair the defect or the deterioration of the corroded pipeline. Fibre-Reinforced Polymer (FRP) composites is one of the effective repair methods in repairing defective pipeline system. FRP composites are lightweight, high performance, suitable to ocean environment, long-lasting and easily to be constructed and tailored to different requirements (Lee and Jain, 2009). However, the performance of this repair system is not fully understood due to several issues which include the complexity of surface preparation, delamination and de-bonding between steel pipe and composite, performance and contribution of the infill material, load transfer mechanism, effect of defect geometries and conservativeness in existing design codes (Lim, 2017). People will have better understanding on the behaviour on the composites by discovering up these issues and this could help to maximise the role and uses of the composite repair system.

## **1.3 Research Problem**

Corrosions could occur at any places of the pipeline including internal and external surfaces of the pipelines and this will reduce the pipe thickness and reduce its strength due to the loss of metal. A low remaining strength may cause the failure of the pipeline and burst may be occurred.

Data such as the presence and the location of the corrosion happened in the pipe or other irregularities on the wall can be taken from the inspection by using the intelligent pig. From the data that are collected from inspection action, it can help in determining the remaining strength of the defective pipeline by referring to several engineering design codes. These include American Society of Mechanical Engineer (ASME) B31G, modified ASME B31G and DNV-RP-F101 codes. The input parameters that are used in these codes include outer diameter of the pipe,  $D$ , wall thickness,  $t$ , yield strength of the

material,  $\sigma_y$  or ultimate tensile strength,  $\sigma_u$ , the length of the defect,  $L$  and the defect depth,  $d$ .

However, the repair codes include ISO/TS 24817 and ASME-PCC2 which are used to determine the repair material only include defect depth as the input parameter in determining the remaining strength of the defective pipe. Hence, investigation on other defect parameters such as defect length is needed to explore the potential effect of defect length towards the burst capacity of a composite repaired pipe.

#### **1.4 Research Objectives**

The aim of this study is to investigate the effect of defect length towards burst capacity of composite repaired pipeline. In order to achieve the aim, two objectives are established as follow:

- 1) To determine the burst pressure of the composite repaired pipeline according to different defect lengths.
- 2) To investigate the effect of defect length upon the burst capacity of composite repaired pipe.

#### **1.5 Research Scope**

The scope of this research concentrates about the effect of remaining strength and the burst capacity of the composite repaired pipe subjected to different lengths. Simulation method which is finite element analysis (FEA) was used where finite element (FE) models were developed to determine the burst capacity of composite repaired pipeline. Variation of other defect geometries such as width and depth are not included in this study.

#### **1.6 Importance of Study**

Repair cost can be reduced by reducing the usage of the composite wrap on the damage pipelines. One of the challenges in optimizing the composite repair design is the lack of information on the behaviour of the composite repaired damaged pipes. Base on the existing assessment codes and previous studies, the defect lengths has been proven to be influential on the remaining strength and the burst capacity of the damaged pipes.



## REFERENCES

- Abdel-Alim, H.E. 2018. Oil and Gas Pipeline Design, Maintenance and Repair – Part 9: Pipe Defects (online). <http://www.eng.cu.edu.eg/users/aelsayed/Part-201-20-Piping-20Systems.pdf>.
- Alang, N.A., Razak, N.A., Shafie, K.A., Sulaiman, A. 2013. Finite element analysis on burst pressure of steel pipes with corrosion defects.
- ASME International. 1991. ASME B31G-1991. Manual for determining the remaining strength of corroded pipelines: a supplement to ASME B31 code for pressure piping.
- ASME International. 2011. ASME PCC-2-2011. Repair of pressure equipment and piping
- Central Intelligence Agency. 2013. The World Factbook (online). <http://www.cia.gov/library/publications/the-world-factbook/geos/us.html>
- Det Norske Veritas (DNV). 2010. Recommended practice DNV-RP-F101. Corroded pipelines.
- ISO. 2006. ISO/TS 24817. Petroleum, petrochemical and natural gas industries – composite repairs of pipework – qualification and design, installation, testing and inspection.
- Khairul Anwar, I. 2012. The effect of corrosion defects on burst pressure of pipelines.
- Lee, L.S., Jain, R. 2009. Clean Techn Environ Policy - The role of FRP composites in a sustainable world. 11:247-249.
- Lim, K.S., Noor, N.M., Azraai, S.N.A. and Yahaya, N. 2015. An overview of corroded pipe repair techniques using composite materials. 10: 19-25.
- Lim, K.S. 2017. Behaviour of repaired composite steel pipeline using epoxy grout as infill material.
- Lim, K.S., Noor, N.M., Azraai, S.N.A., Yahaya, N., Zardasti, L. and Kim, J.J. 2019. Behaviour of steel pipelines with composites repair analysed using experimental and numerical approaches. 139: 321-333.
- Mohamad Zulfadli, M.R. 2012. Determination of burst pressure of defective steel pipes using finite element analysis.

National Association of Manufacturers. 2015. America's Oil Pipelines: Fueling Manufacturing Jobs and Growth (online). [http://www.nam.org/Issues/ Energy-and-Environment/Crude-Oil-Pipeline-One-Pager.pdf](http://www.nam.org/Issues/Energy-and-Environment/Crude-Oil-Pipeline-One-Pager.pdf)

Saravanan, K., Azmi, A.W., Santosh, P. and Mohamad Armiya, Z. 2014. Estimation of burst pressure of corroded pipeline using finite element analysis (FEA).

Windham, T. 2018. Victims of Taiwan's 2014 Kaohsiung Gas Explosion speak of moving past the blast. Taiwan News. 11 May.